

SLOW SPEED CATCHES

Predictive Wins from Food & Beverage Facilities

© 2022 KCF Technologies Inc.

Cam Shaft Drive Gearbox



Asset Type:

Cam Shaft Gearbox

Asset Info:

Speed: 30 rpm


Part Lead Time: 4 weeks

Event Info:

Specialty gearboxes are often custom designed, with long lead times. A worn gearset can interrupt operations for weeks at a time, with major financial implications.

Sample Frequency:

KCF wireless vibration sensors can be switched between multiple sampling frequency options at any time, ranging from 64 Hz to 8192 Hz, allowing for analysis on high & low speed equipment.



Dryer Trunnion Bearing



Asset Type:

Dryer Drum Trunnion Bearing

Asset Info:

Speed: 5 rpm


Event Info:

Bearings are known to fail very quickly once damage occurs – matter of hours


Because this was known, very tight alarm settings were used. An inspection was recommended off only 2 high vibration samples

Power of Comparison

Comparing temperature to other bearings on the same dryer, bearing in question showed clear evidence that it was failing



Temperature Comparison



Bucket Elevator Bearing





Asset Info:

Speed: 40 rpm

Part Lead Time: 4 weeks

σ

Elevator Height: 300ft

Collateral Damage if left unchecked:


Bearing fire

Complete belt failure


Structural damage



Frequency Spectrum



Time Waveform



Belt Conveyor Bearing



Temperature 🖊 Peak Acceleration 🖊

Asset Type:

Belt Elevator Bearing

Asset Info:

Speed: 400 rpm

Event Info:


Bearing first called out for vibration increase

Field inspection found no issues, continued to operate as normal

Two weeks later, temperature spiked to over 225 F without much change in vibration

Root Cause:

Bearing had run out of grease. Bearing replaced



Time Waveform

